

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

CR477  
NW  
1/2-1  
0.747 mi.  
3942 ft.

VAULT # 7251  
BAY 46TH ST/CROPSY AVE  
BROOKLYN, NY

NY Spills S104952121  
N/A

Site 3 of 3 in cluster CR

Relative:  
Higher

Actual:  
4 ft.

SPILLS:

Name: VAULT # 7251  
Address: BAY 46TH ST/CROPSY AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0011179 / 2001-04-18  
Facility ID: 0011179  
Facility Type: ER  
DER Facility ID: 92200  
Site ID: 104330  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2001-01-13  
Investigator: JHOCONE  
Referred To: Not reported  
Reported to Dept: 2001-01-13  
CID: 281  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Affected Persons  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2001-01-13  
Spill Record Last Update: 2001-08-14  
Spiller Name: Not reported  
Spiller Company: UNKNOWN  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: JIM FOX  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was O'CONNELL CON ED E2MIS REPORT 1-13-01 Approx. 3gals. of unknown oil on concrete floor. Unit is defective, crew to test unit. Env. tag placed and one sample taken from spill. Historical records indicate 0ppm Nov.1998. Concrete sump, no pump. LSN 01-00374 <1ppm Analysis indicates the presence of combustible gases usually associated with an electrical burn-out. Unit has been removed. 1-28-01 17:45hrs.

Remarks:

Cleanup is completed and tag removed. A cemented sump found. Structure was double washed with slix, liquids removed by tanker and solids by vactor. No leaking company equipment. Incident is closed."  
"ABOVE MATERIAL DISCOVERED AT ABOVE LOCATION SPILLED ON CONCRETE. SAMPLE HAS BEEN TAKEN AND CLEANUP IS PENDING RESULTS. CON ED # 135081. NO CALL BACK REQUESTED."

All Materials:

Site ID: 104330  
Operable Unit ID: 833247  
Operable Unit: 01  
Material ID: 541502  
Material Code: 0066A

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 3.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported